

	Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1380	(fishing near3 (rod\$1 pole\$1)) near10 holder\$1	US-PGPUB; USPAT	2005/04/12 12:21			
2	BRS	L2	75	1 same (alarm\$1 alert\$3 warn\$3)	US-PGPUB; USPAT	2005/04/12 12:21			
3	BRS	L3	69	1 same (switch\$2 sensor\$1 detector\$1)	US-PGPUB; USPAT	2005/04/12 12:23			
4	BRS	L5	22	2 same 3	US-PGPUB; USPAT	2005/04/12 12:21			
5	BRS	L4	33	2 and 3	US-PGPUB; USPAT	2005/04/12 12:22			
6	BRS	L6	32	1 near10 (switch\$2 sensor\$1 detector\$1)	US-PGPUB; USPAT	2005/04/12 12:22			
7	BRS	L7	45661	(alarm\$1 alert\$3 warn\$3) near10 (switch\$2 sensor\$1 detector\$1)	US-PGPUB; USPAT	2005/04/12 12:23			
8	BRS	L8	54	1 and 7	US-PGPUB; USPAT	2005/04/12 12:23			
9	BRS	L10	19	2 and 6	US-PGPUB; USPAT	2005/04/12 12:24			
10	BRS	L9	20	1 same 7	US-PGPUB; USPAT	2005/04/12 12:24			